



Photograph 17: Looking north-west from Morestead Road near Deacon Hill (elevation of viewpoint 120m). Note steeply falling ground allows clear view over Winchester in direction of Barton Farm. Intervening buildings largely conceal direct view of site. Sewage works visible in middle distance.



Photograph 18: looking north from summit of St. Catherine's Hill (elevation of viewpoint 93m). Note St Catherine's Hill gives a clear view over Winchester and the downland to the north, but intervening buildings and landform (including the ridge immediately south of Barton Farm) almost completely conceal the site from view.

## Photographs 17-18

## Visual Analysis Photographs

Figure No. 11.5