



Photograph 11: Looking north along Andover Road.
Note young and semi-mature trees in eastern highway verge and discontinuous hedgerow.



Photograph 12: Looking south along Andover Road.
Note residential boundary hedgerows on right of view and bank adjoining carriageway with mature sycamore trees.

Photographs 11-12

**Visual Analysis
Photographs**

Figure No. 11.5